

Nortel Networks™

Technical Support

Customer Support Bulletin

Number: CSB- 0107002

Released: 7/30/2001

Subject: Passport runtime software 2.0.7.6 is now available

Product:

Product Name / Designation(s)	Model/Order Number(s)	Part Number(s)	Model Functional REVISION Number(s)	
			Potentially Affected	Corrected
Passport Runtime (software)	N/A	N/A	2.0.7.4 and 2.0.7.5	2.0.7.6
Passport (Accelar) 1108TX –C 8 port 10 Base-T/100 Base-TX Ethernet interface module	DJ1404090	N/A	ALL	N/A

Description:

Passport Runtime software version 2.0.7.6 resolves the failure to pass 10Mb/s traffic which was apparent while running Passport Runtime software version 2.0.7.4 or 2.0.7.5.

Discussion:

Passport (Accelar) 1100/1150 Routing Switches running Passport Runtime software 2.0.7.4 and 2.0.7.5 will not program the Passport (Accelar) 1108TX-C Module ICS chip registers correctly. The link integrity light is active (lit) but 10Mb/s traffic will not be passed. This issue affects only 10Mb/s traffic. All ports connected to 100Mb/s devices are not affected by this issue and will work properly.

Passport runtime software version 2.0.7.6 enables the proper programming of the Passport (Accelar) 1108TX-C ISC chip registers and allowing for the passing of 10Mb/s traffic on the Passport (Accelar) 1108TX-C.

Resolution:

Passport runtime software version 2.0.7.6 fixes the issue by enabling the proper programming of the Passport (Accelar) 1108TX-C ISC chip registers and allowing for the passing of 10Mb/s traffic. Customers who wish to obtain Passport runtime software version 2.0.7.6 should contact Nortel Networks Technical Support.

Replacement of product (hardware) is not warranted or authorized to correct the issue described in this bulletin.

Support Contact Information:

Nortel Networks is committed to bettering the customer experience through its Customer TouchPoint Program (CTP) – where in most countries one number can be used to contact Nortel Networks. To obtain regional telephone contact information, please visit the following website: <http://www.nortelnetworks.com/help/contact/global/>.